


Ronix[®]

Premium Quality


DRYWALL SCREWDRIVER 2507



SPECIFICATIONS

Model	2507
Voltage	220V-240V
Max. Torque	13N·m
Frequency	50-60Hz
Power	450W
Driving Shank	HEX
Weight	1.55Kgs
Supplied In	Ronix Color Box
Driving Shank Size	6.35mm
No-Load Speed	0-4000RPM

PARTS LIST



SAFETY NOTES

GENERAL POWER TOOL SAFETY WARNINGS

WARNING!

Read all safety warnings and all instructions. Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury.

WORK AREA SAFETY

- Keep work area clean and well lit. Cluttered or dark areas invite accidents.
- Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust. Power tools create sparks which may ignite the dust or fumes.
- Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.

ELECTRICAL SAFETY

- Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools. Unmodified plugs and matching outlets will reduce risk of electric shock.
- Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators. There is an increased risk of electric shock if your body is earthed or grounded.
- Do not expose power tools to rain or wet conditions. Water entering a power tool will increase the risk of electric shock.
- Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges and moving parts. Damaged or entangled cords increase the risk of electric shock.
- When operating a power tool outdoors, use an extension cord suitable for outdoor use. Use of a cord suitable for outdoor use reduces the risk

of electric shock.

- If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply. Use of an RCD reduces the risk of electric shock.

PERSONAL SAFETY

- Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.

- Use personal protective equipment. Always wear eye protection. Protective equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.

- Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool. Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.

- Remove any adjusting key or wrench before turning the power tool on. A wrench or a key left attached to a rotating part of the power tool may result in personal injury.

- Do not overreach. Keep proper footing and balance at all times. This enables better control of the power tool in unexpected situations.

- Dress properly. Do not wear loose clothing or jewelry. Keep your hair, clothing and gloves away from moving parts. Loose clothes, jewelry or long hair can be caught in moving parts.

- If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used. Use of dust collection can reduce dust-related hazards.

POWER TOOL USE AND CARE

- Do not force the power tool. Use the correct power tool for your application. The correct power tool will do the job better and safer at the rate for which it was designed.
- Do not use the power tool if the switch does not turn it on and off. Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- Disconnect the plug from the power source and/or the battery pack from the power tool before making any adjustments, changing accessories, or storing power tools. Such preventive safety measures reduce the risk of starting the power tool accidentally.
- Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool. Power tools are dangerous in the hands of untrained users.
- Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use. Many accidents are caused by poorly maintained power tools.
- Keep cutting tools sharp and clean. Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- Use the power tool, accessories and tool bits etc. in accordance with these instructions, considering the working conditions and the work to be performed. Use of the power tool for operations different from those intended could result in a hazardous situation.

SERVICE


- Have your power tool serviced by Ronix Service Center This will ensure that the safety of the power tool is maintained.

SAFETY WARNINGS FOR SCREWDRIVERS


- Wear ear protectors when impact drilling. Exposure to noise can cause hearing loss.
 - Use auxiliary handle(s), if supplied with tool. Loss of control can cause personal injury.
 - Hold power tool by insulated gripping surface, when performing an operation where the cutting accessory may contact hidden wiring or its own cord. Cutting accessory contacting a “live” wire may make exposed metal parts of the power tool “live” and could give the operator an electric shock.
 - Always be sure you have a firm footing. Be sure no one is below when using the tool in high locations.
 - Hold the tool firmly with both hands.
 - Keep hands away from rotating parts.
 - Don't leave the tool running. Operate the tool only when hand-held.
 - Don't touch the bit or the work piece immediately after operation; they may be extremely hot and cold burn your skin.
 - Some material contains chemical which may be toxic. Take caution to prevent dust inhalation and skin contact.
- Follow material supplier safety data.

USAGE


- By pressing the switch, the device turns on and by removing the hand from the switch, the device turns off



- To use the device continuously, press the on/off switch to start the machine and then press Lock-on button switch after that, no need to hold the switch anymore it can work continuously.



- Speed control for smooth starting




- Variable speed control switch to adjust speed conveniently relate to your work




CHANGING DIRECTION OF ROTATION

- when not properly set in left/right position, switch A cannot be activated
- change direction of rotation only when tool is at a complete standstill



DEPTH ADJUSTMENT

- The depth can be adjusted by turning the adjusting sleeve. Turn it in “B” direction for less depth and in “A” direction for more depth.



- Stop adjusting when the edge of adjusting sleeve reaches the limit line (the recessed area on the locator). When the adjusting sleeve exceeds the limit line, it may fall from the machine and it can be installed back easily.
- do not use bits with a damaged shank

HOLDING AND GUIDING THE TOOL

- while working, always hold the tool at the grip area(s)
- keep ventilation slots uncovered
- do not apply too much pressure on the tool; let the tool do the work for you



www.ronixtools.com